

Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



WORK ORDER INFORMATION

Work Order Name: WO/80008KN0741/1

Work Order Type: Weatherization

Audit Name: 80008KN0741-Audit

CLIENT INFORMATION

Client Name:

Address:

Client ID: 80008KN0741

Alt. Client ID: Knox

AGENCY INFORMATION

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number:	 	 	•	 w	
Contractor's Signature:					

COMMENT

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

House built in 1945

An EPA Certified Firm/Renovator is required.

Measures

1	Measure 1	Broken Pane (upto 10 squ e3,w4,	are feet)		Componen	ts			Inspected
С	omment Ref Fie	fer to Appendix A- Standards Id Guide.	for Weath	erizati	on Materials	and So	utheast		
					Estimated	•		Actual	
#	Material / Lab	or Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Unspecified	Broken Pane (upto 10 square feet) (+)	Each	2	Total Control of the				
2	Labor	labor	Each	2					
C	ther Detail	_							
Г								[][
L.	-		L				_	[
			i	Measur	Sub Total:			Sub Total:	
	Fleld Notes:			,		,,	ra		

Page 2 of 12

	Measure 2 Mas	tic the Return Box			Componen	ts			Inspected
C	Use foar return bo allowed.	hite Mastic to be applied m board around edges to ox where it meets return i Refer to Appendix A- Sta st Field Guide.	fill in any egister w	voids ith ap	and mastic. propriate cau	Seal fro	nt of nanges		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Mate	Mastic the Return Box	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.				7			
2	Labor	Labor	Each	1					
C	Other Detail								
L									
			ı	Measur	e Sub Total:			Sub Total:	
	Fleld Notes:			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			-		

Page 3 of 12

	Measure 3 Mas	stic/Insulate Supply Bo	ot qty 7		Componen	ts			Inspected
C	be insulcell foar be insulcell foar bedraids Bdrm1S bdrm2S Bath1S Living F Dining F	white Mastic to be applied where it meets subfloor lated on outside of boot in. Location+Register Ty Supply2.7 Supply3.9 LoomSupply2.1 RoomSupply0.7 RoomSupply0.9 Supply1.9	to be caulk to R-6. This	ed wit s is be	of boot to se h appropriate st performed	al all sea	Boots t	O	
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Unspecified	Mastic/Insulate Supply Boot (+)	Each	7		****			
2	Labor	labor	Each	7					
C	Other Detail								
L						****]

				/leasure	Sub Total:)	Sub Total:	
	Fleid Notes:		71			W	, , , , , , , , , , , , , , , , , , , ,		

Measu		indow Glazing ,e2,e3,e4,e5,n3,s1,w3,w4	,w5		Componen	its		s	Inspected
Comme	New g	se glazing must be 100% i lazing should be even, sm ndards for Weatherization	ooth, and	all lool	k uniform. R	efer to A	Appendix	<	
	NOTE	: Silicone, caulk, or any otl	ne						
					Estimated	1		Actual	
# Materia	al/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Unspe	cified	Window Glazing (+)	Each	10		700			
2 Labor		labor	Each	10					
Other De	tall								
			1	Measur	e Sub Total:] :	Sub Total:	
Field No	otes:			***			<u> </u>		

Report Run On: 5/7/2010

	Measure 5 DW Comment	/H Pipe Insulation			Componen	ts		, market	Inspected
					Estimated	•		Actual	<u> </u>
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
		Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.					i		
2	Labor	DHW Pipe Insulation	Each	1					
C	Other Detail								
L									
			ı	Measur	e Sub Total:			Sub Total:	
	Field Notes:					,		L	

	Measure 6	Flo	or Ins. R-19			Componen	ts F1			Inspected
Comment •Includes labor cost. Contractor's responsibility to seal penetration in floor before installing insulation. Contractor to install using Resnet Grade 1 Standards. Insulation is installed to maintain permanent contact with the subfloor above (paper side against subfloor) including necessary supports (e.g. staves for blankets). Insulation to have NO gaps, voids, or compressions. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide. Estimated Actual										
						Estimated			Actual	
#	Material / La	bor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation		Floor Insulation <i>-</i> Fiberglass Batts - R-19	SqFt	1150					
2	Labor		Floor Insulation - Fiberglass Batts - R-19	SqFt	1150					
C	ther Detail									
		mn								
				4	Measure	Sub Total:		S	ub Total:	
	Field Notes:									

Report Run On: 5/7/2010

	Measure	7	Attic	Ins. R-30				Componer	its A1			,	Inspected
•	Comment	atti acci ins silic acci Gra	ic spa cess. fit an ulatin cone cess a ade 1	ice showing of Install baffle dovering verge. Seal arou or fire resistand weather Standards.	ost. Contractor to install 1 ruler for every 300 square foot of ring depth of insulation. Build insulation dam around attic affles as needed to prevent loose fill insulation from entering no vent. Seal all holes, gaps, and penetrations in attic before around chimney with sheet metal and high temperature sistant foam. Install R-30 fiberglass batt secured to attic ther strip with foam tape. Contractor to install using Resnet ds. Refer to Appendix A- Standards for Weatherization butheast Field Guide.						,		
								Estimated	<u> </u>			Actual	
#			or	Description /		Units	Qty	Unit Cost	Total	G	aty	Unit Cost	Total
1	Insulation	1		Attic Insulation Fiberglass -		SqFt	504		700				
2	Labor			Attic Insulation		SqFt	504						
2	Other Detail	!											
L		-											
L									7012				
r	-					ı	Measur	e Sub Total:			\$	Sub Total:	
	Field Note	s:										101	

DOE Weatherization Assistant Version 8.6.0 Page 8 of 12

	Measure 8 DWI	Tank Insulation			Componen	ts		- ,,,,,,,,	Inspected
C	comment extend p	ressure relief pipe as ne	eded		•				
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							***************************************
2	Labor	DHW Tank Insulation	Each	1					
2	Other Detail								
				Measur	e Sub Total:			Sub Total:	
F	Field Notes:			 .	<u></u>	J	***	L.	

	Southea	Refer to Appendix A- State Ist Field Guide.	andards fo	r Wea	to fireplace of the the fixed the fi	aterials a	nd		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total		Actual	T ()
1	Health and Safety		Each	1		1 Otal	Qty	Unit Cost	Total
		It is the responsibility of the contractor to plug fireplace with wooden plug and seal with 1/2" plywood painted owner's choice. Caulk must be same color as paint .Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
0	ther Detail					L		L	
		,		leasure	Sub Total:		! S	 Sub Total: ☐	

	Measure 10 CO	Monitor is Needed		Components					
C	omment Refer to Field Gu	Attachment A- Standard uide.	s for Wea	theriza			outhea	st	Inspected
					Estimated	•		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.				,	J [
2	Labor	Labor	Each	1					
0	ther Detail								***
			A	/leasure	Sub Total:	71.		Sub Total:	
	Field Notes:			70.1		9633. pp.	I	L	

	Measure 11 Fix Exh	Improper Venting of Ba aust Fan	throom		Componen	ts		Inspected
C	comment Bath Ve Attachm Guide.	ents installed to outside o nent A- Standards for We	f home. No eatherizatio	o chan on Mat	iges allowed. erials and So	Refer to	o Field	
					Estimated		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty Unit Co	st Total
1	Health and Safety	Bath Vent w/ Piping to Outside	Each	1				
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.						
2	Labor	Labor	Each	1				
0	ther Detail	_						
		N 11VL 772		[]	0.4.7.4.4			
	Field Notes:			neasure	Sub Total:		Sub Total:	
			Work Ora	ler Graı	nd Total:		Grand Total:	